
St. John's Episcopal Church



#### March 19, 2024

## St. John's Episcopal Church

Facility Condition Assessment and Reserve Study/Fixed Asset Replacement Budget



## **RECMP** Team

- Fran Anderson, Partner • RECMP
- Scott Sider, Sr. Project Manager
  Michael Graves Architecture and Design
- Nicole Miletti
  - Michael Graves Architecture and Design

## Engagement

#### Facility Condition Assessment

- Conducted a thorough inspection of all facilities and grounds
- All condition assessments are based upon observable conditions
- Did not include any invasive or destructive investigation
- Did not include repairs under \$10,000 unless requested by St. John's

#### Condition Assessment Report

- Identify Major Areas of Concern
- A list of immediate and short term repairs not included in the Asset Replacement Budget
- A list of any recommended additional testing outside the scope of this engagement

#### Fixed Asset Replacement Budget and Reserve Study

• A schedule of major (non-routine) repair and replacement costs to be anticipated over the next 20 years for budgetary and planning purposes; the Asset Replacement Budget and Reserve Schedule

#### Types of Capital Expenditures

Renewals and<br/>ReplacementsFOCUSAlterations and<br/>RenovationsFOCUSAdditions and<br/>AcquisitionsFUTURE TOOL

#### **Capital Renewal and Replacements**

Planned work to <u>extend</u> the life of an existing fixed asset beyond its initial service life <u>or</u> to replace an existing fixed asset with a new asset of the *same capacity* to perform the *same function*.

Due Diligence and Records Review

- Pre-Survey Questionnaire
- Interview key facilities personnel, vendors and contractors regarding past facility maintenance, repairs, upgrades and concerns
- Review available construction documents and maintenance files, including Preventive Maintenance agreements and repair contracts
- Review past/proposed capital budgets and expenditures to understand major improvements that have been made or are proposed

Site Inspection

- Beginning in November, RECMP conducted detailed site inspections of the buildings and grounds
- Focused on building envelope (roof, walls, windows, foundation); heating/cooling, plumbing, and electrical systems; site paving and storm water management; vertical transportation; and general exterior and interior conditions.

**Report Organization** 

- The Condition Assessment report and Fixed Asset Replacement Budget are broken down by individual buildings and then grouped as part of either the Church or the School, as follows:
  - Church Buildings and Site
    - Site includes all site improvements
    - Historic Church
    - Alda's Chapel
    - Rose Hill
    - Clark House
    - Parish Life Center
    - 3497 Chatham Road Residence
    - Maintenance Shed
  - School Buildings
    - CME 2001 Additions includes all HVAC equipment for all school buildings
    - Carter Education Building
    - Parish House Auditorium and Media Center

Assessment of Existing Physical Conditions

#### **Existing Physical Condition**

- Based on observations, interviews and document review, RECMP defines the physical condition of building components in one of three categories; Good, Fair, or Poor, each with the following definitions:
- **Good** The component is in satisfactory condition for its age and, for budgeting purposes, should only require regular or routine maintenance until its scheduled replacement.
- Fair The component is in satisfactory condition for its age, but repair or accelerated replacement may be required during the assessment period.
- **Poor** Immediate repair, significant maintenance, or immediate replacement is required.

**Condition Assessment** 

Example: DOAS AHU-1

Example: DOAS AHU-1

Identify the following:

RECMP

- Year Placed in Service 2014
- Condition Good
- Estimated Useful Life (EUL) 20
- Effective Age 9
- Remaining Useful Life (RUL) 11 years

10

Component or System	Placed in Service (Year)	Condition	EUL	Effective Age	RUL	Qty	\$/Unit	Cycl	e Replacment	Replace %	Year 11
DOAS AHU-1	2014	Good	20	9	11	1 \$	250,000	\$	250,000	100%	\$250,000

20 Year Fixed Asset Replacement Budget Example: DOAS AHU-1

- Replacement Cost Estimate based on existing proposals, industry publications such as RS Means, original cost plus escalation, or consultant's knowledge
- Replacement % defined as percentage of cost required at time of scheduled replacement multiplied by the number of times the asset is scheduled to be replaced during the 20 year period.
- Components or portions of an asset may be replaced rather than the full replacement to extend the asset's useful life. Ex. Replace the cooling coils on an air handler rather than the entire unit.

Summary

The property and buildings are generally found to be in **Good to Fair** condition based on the effective age of each evaluated component and system. However, several building components across multiple buildings were found to be in **Poor** condition and a few require immediate repair or replacement.

# Findings Summary

#### Facility Assessment Summary Table

Physical Condition Summary	Good	Fair	Poor
Site	V		
Historic Church		V	
Alda's Chapel	٧		
Rose Hill		V	
Clark House	V		
CME - 2001 Additions	V		
Carter Education		V	
Parish House - Auditorium/Media Center		V	
Parish Life Center		V	
Chatham House	V		
Maintenance Shed			V

20 Year Asset Replacement Budget Total – Current Total and Escalated Total

Financial Summary	<u>Total Current Value</u>	Escalated Total
Replacement Budget Total – All Buildings	\$2,726,243	\$4,634,990
Church Buildings and Site Only	\$1,471,730	\$2,553,457
School Buildings Only	\$1,254,513	\$2,081,533

• Asset Replacement Budget provides the annual expense in both today's dollars and escalated over time for inflation

- Escalation/Inflation Rate is 6% year over year
- Identifies yearly Reserve Requirement
- Treatment of building masonry and slate roofs

20 Year Asset Replacement Budget by Building with Immediate and Short Term Repairs

	F	Replacement	9	Short Term
Financial Summary	Reserves		Repairs	
Site	\$	354,900	\$	1,550
Church	\$	729,250	\$	35,000
Alda's Chapel	\$	31,050	\$	4,500
Rose Hill	\$	122,250	\$	8,425
Clark House	\$	84,460	\$	1,025
СМЕ	\$	1,086,113	\$	10,900
Carter Education	\$	101,400		
Auditorium/Media Center	\$	67,000	\$	450
Parish Life	\$	102,500	\$	2,625
Chatham House	\$	28,300	\$	9,575
Maintenance Shed	\$	19,020	\$	4,500
Total	\$	2,726,243	\$	78,550
Financial Summary		Total CV	Es	calated Total
Immediate Repairs	\$	59,500		
Short Term Repairs	\$	19,050		
Replacement Reserves	\$	2,726,243	\$	4,634,990

Immediate and

#### Years 1-5 Major Replacement Costs

	1	2	3	4	5
Total Annual Expense (Uninflated)	\$447,913	\$508 <i>,</i> 950	\$76,150	\$79,900	\$137,450
Inflation Factor	1.0000	1.0600	1.1236	1.1910	1.2625
Total Annual Expense (Inflated)	\$447,913	\$539 <i>,</i> 487	\$85 <i>,</i> 562	\$95,162	\$173,527
Annual Reserve	Annual Reserve	to be completed	with Owner -		

#### Years 15-17 Major Replacement Costs

	15	16	17
Total Annual Expense (Uninflated)	\$138,650	\$243,450	\$421,050
Inflation Factor	2.2609	2.3966	2.5404
Total Annual Expense (Inflated)	\$313,474	\$583,442	\$1,069,615
Annual Reserve			

## Findings

20 Year Capital Replacement Budget

Years 1-5 Major Replacement Costs

Years 15-17

Additional Concerns and Recommendations

During the course of the Assessment, several other concerns were identified by the Consultants and staff that should be addressed by staff or through additional investigations and testing by outside consultants.

## Additional Areas of Concern and Testing Recommendations (examples):

Item	Consultant/Contractor	Recommendations	Cost
Church Envelope	Stained Glass	Inspect and create repair budget	\$2,500
		Verify ceiling separation requirement between classrooms and	
Carter Education	Architect/Fire Protection	attic space	\$750

## Findings

Additional Concerns and Testing Recommendations (Cont'd.)

## Questions

?

# Thank You!